

APPENDIX D
PHOTOGRAPHS OF ORE DEBRIS SITES

REPRESENTATIVE PHOTOGRAPHS FOR SITE 2004A



Excavation of individual and scattered ore rocks. Painted and flagged areas of high concentrations of ore present in foreground.



Placement of fill along slope after excavation.



Excavation along toe of slope. All excavations on this site were backfilled with clean fill.



Top of berm looking west.

REPRESENTATIVE SITE PHOTOGRAPH FOR SITE 2005A



Hand excavation of single ore rock. Site was regraded after ore and soil were removed from site.

REPRESENTATIVE SITE PHOTOGRAPHS FOR SITE 4-001



Looking east. Excavation on south side of road just west to cattle guard



Looking west. Backfilling on south side of road in the area of the cattle guard.



Looking south. Excavated area on north side of road.



Looking west. Excavated area on south side of road.



Looking south. Excavation in progress on north side of road.

REPRESENTATIVE SITE PHOTOGRAPHS FOR SITE 4-002



Excavation 4-002 looking northwest, toward western edge of excavation. Site was eventually backfilled with clean fill and compacted




Area 4-002 looking southeast after placement of clean fill.



Area 4-002 looking southeast toward eastern edge of excavation after placement of clean fill.

REPRESENTATIVE PHOTOGRAPHS FOR SITE 5-001



North side of highway, looking west. Clean fill placed on excavation. Compaction and grading was completed on loose fill.



Excavation along south side of highway – looking west. Fill was placed in excavation prior to taking this photo



Excavation along south side of highway – looking east. Photo depicts extent of excavation along south side.

REPRESENTATIVE PHOTOGRAPHS FOR SITE 33-001



Looking towards Wellpinit, excavation in progress.



Looking towards Wellpinit. Excavated area with dumped backfill in foreground.



Looking towards Wellpinit. Backfill completed.

REPRESENTATIVE SITE PHOTOGRAPHS FOR SITE 33-003



Excavation in progress.



Looking towards mine. Excavated area.



Looking towards mine. Backfill completed.

REPRESENTATIVE PHOTOGRAPHS FOR SITE 33-007



Excavation of 33-007 looking west, along south end of highway.



Excavation into south end of roadcut. Excavated terminated approximately 29 inches from top of original roadcut.



Final grade and finished site, looking west.



Excavated and stockpiled soil. Site was eventually backfilled with clean fill and compacted.



Dust control used during the loading of soil and ore into haul trucks.

REPRESENTATIVE SITE PHOTOGRAPHS FOR SITE 33-008



Excavation in progress. Looking south.



Excavation and grading completed. Looking towards Wellpinit

REPRESENTATIVE SITE PHOTOGRAPHS FOR SITE 33-009



Excavation in progress. Looking north.



Excavation in progress. Looking north.



Excavation and grading completed. Looking north.

REPRESENTATIVE SITE PHOTOGRAPH FOR SITE 34-003



Photo of soil and individual ore rock being placed in 20-mil bag. Utility marker present in background.

REPRESENTATIVE PHOTOGRAPHS FOR SITE 35-004



Hand excavation of ore rock. Soil placed in 20-mil plastic bags.



Bags from excavation of ore rock and soils placed in 20-mil bags.